

**Flood Control Project Maintenance  
Levee Inspections**

**Fall 2008 Levee Maintenance Deficiency Summary Report**

**Overall LMA & Unit Ratings, including Boat Survey Erosion**

**Sacramento River Basin**

<b>RD1001</b>	Overall LMA Rating	Total LMA Miles				
<b>Reclamation District No. 1001</b>	<b>M</b>	<b>44.00</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Vegetation	5.45		5.45	12.39%		
Trim / Thin Trees	0.11		0.11	0.25%		
Encroachments	0.57		0.57	1.30%	0.16	0.05
Animal Control	0.02		0.02	0.05%		
Slope Stability	0.03		0.03	0.07%		
Sluice / Slide Gates	0.01		0.01	0.02%		
Boat Survey Erosion	0.03	0.04	0.19	0.43%		
<i>LMA Totals:</i>	6.22	0.04	6.38	14.50%	0.16	0.05

  

<b>Unit No. 01 Yankee Slough</b>	Overall Unit Rating	Total Unit Miles				
	<b>A</b>	<b>4.20</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Encroachments	0.12		0.12	2.86%	0.06	0.01
Slope Stability	0.01		0.01	0.24%		
<i>Unit Totals:</i>	0.13	0.00	0.13	3.10%	0.06	0.01

  

<b>Unit No. 02 Yankee Slough</b>	Overall Unit Rating	Total Unit Miles				
	<b>U</b>	<b>3.70</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Vegetation	1.72		1.72	46.49%		
Encroachments	0.14		0.14	3.78%	0.02	0.02
<i>Unit Totals:</i>	1.86	0.00	1.86	50.27%	0.02	0.02

  

<b>Unit No. 03 Bear River</b>	Overall Unit Rating	Total Unit Miles				
	<b>M</b>	<b>12.60</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Vegetation	1.12		1.12	8.89%		
Encroachments	0.30		0.30	2.38%	0.02	
Animal Control	0.02		0.02	0.16%		
Slope Stability	0.02		0.02	0.16%		
Boat Survey Erosion		0.04	0.16	1.27%		
<i>Unit Totals:</i>	1.46	0.04	1.62	12.86%	0.02	0.00

  

<b>Unit No. 04 Feather River</b>	Overall Unit Rating	Total Unit Miles				
	<b>M</b>	<b>13.30</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Vegetation	1.95		1.95	14.66%		
Trim / Thin Trees	0.11		0.11	0.83%		
Encroachments	0.01		0.01	0.08%	0.03	0.01
Boat Survey Erosion	0.03		0.03	0.23%		
<i>Unit Totals:</i>	2.10	0.00	2.10	15.79%	0.03	0.01

**Flood Control Project Maintenance  
Levee Inspections**

**Fall 2008 Levee Maintenance Deficiency Summary Report**

**Overall LMA & Unit Ratings, including Boat Survey Erosion**

***Sacramento River Basin (cont.)***

Unit No. 05 Natomas Cross Canal	Overall Unit Rating	Total Unit Miles				
	<b>A</b>	<b>5.40</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Encroachments						0.01
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.01

  

Unit No. 06 East Side Canal	Overall Unit Rating	Total Unit Miles				
	<b>M</b>	<b>4.80</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Vegetation	0.66		0.66	13.75%		
Encroachments					0.03	
Sluice / Slide Gates	0.01		0.01	0.21%		
<i>Unit Totals:</i>	0.67	0.00	0.67	13.96%	0.03	0.00

**Flood Control Project Maintenance  
Levee Inspections**  
**LMA District Cover Sheet**  
**Fall 2008 Levee Inspection Results**

**Reclamation District No. 1001**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)			M	

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\*  
SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2008 Levee Inspection Results**

**Reclamation District No. 1001**

Waterway		Bank	Unit Miles
Unit No. 01 Yankee Slough		Right	4.20

  

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	3/20/2008		9/24/2008	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

## Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


X

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2008**

**Reclamation District No. 1001**

Waterway						Bank	Unit Miles	Inspection Date		Inspector	
Unit No. 01 Yankee Slough						Right	4.20	09/24/2008		Clay Thomas	
LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.60	0.60	Earthen Levee	Encroachments	LS	M	Prunings	38.975105 ° -121.478247 °	38.975105 ° -121.478247 °		18
2	0.93	0.93	Earthen Levee	Encroachments	LS	M	Prunings	38.974670 ° -121.484230 °	38.974670 ° -121.484230 °		16
3	0.96	0.96	Earthen Levee	Encroachments	LS	CO	Landscaping	38.974569 ° -121.484815 °	38.974569 ° -121.484815 °		15
4	1.31	1.31	Earthen Levee	Encroachments	LS	M	Prunings	38.972670 ° -121.490550 °	38.972670 ° -121.490550 °		14
5	1.54	1.54	Earthen Levee	Encroachments	LS	M	Debris	38.970683 ° -121.493833 °	38.970683 ° -121.493833 °		13
6	1.61	1.61	Earthen Levee	Encroachments	LS	M	Debris	38.970510 ° -121.495195 °	38.970510 ° -121.495195 °		12
7	1.83	1.83	Earthen Levee	Slope Stability	LS	M	Repair slope instability.	38.971082 ° -121.499118 °	38.971082 ° -121.499118 °		11
8	2.03	2.03	Earthen Levee	Encroachments	LS	M	Prunings	38.971150 ° -121.502780 °	38.971150 ° -121.502780 °		10
9	3.01	3.01	Earthen Levee	Encroachments	LS	M	Prunings	38.966612 ° -121.518898 °	38.966612 ° -121.518898 °		6
10	3.16	3.22	Earthen Levee	Encroachments	LS	PO	Landscaping	38.965663 ° -121.521023 °	38.965705 ° -121.522098 °		5
11	3.20	3.24	Earthen Levee	Encroachments	LS	M	Debris	38.965688 ° -121.521800 °	38.965720 ° -121.522550 °		4
12	3.35	3.35	Earthen Levee	Encroachments	LS	M	Debris	38.965585 ° -121.524458 °	38.965585 ° -121.524458 °		3

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2008 Levee Inspection Results**

**Reclamation District No. 1001**

Waterway		Bank	Unit Miles
Unit No. 02 Yankee Slough		Left	3.70

  

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	3/20/2008		9/24/2008	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By				
Unit Maintenance Rating (Fall Only)			U	

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

## Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


X

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2008**

**Reclamation District No. 1001**

Waterway						Bank	Unit Miles	Inspection Date		Inspector	
Unit No. 02 Yankee Slough						Left	3.70	09/24/2008		Clay Thomas	
LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.04	0.90	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.971242 ° -121.474029 °	38.973375 ° -121.487429 °		13
2	0.04	0.90	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.971244 ° -121.474031 °	38.973378 ° -121.487427 °		14
3	0.08	0.08	Earthen Levee	Encroachments	LS	M	Prunings	38.971837 ° -121.474000 °	38.971837 ° -121.474000 °		3
4	0.24	0.33	Earthen Levee	Encroachments	LS	M	Prunings	38.973947 ° -121.475518 °	38.974555 ° -121.477083 °		4
5	0.52	0.52	Earthen Levee	Encroachments	LS	M	Debris	38.974325 ° -121.480495 °	38.974325 ° -121.480495 °		5
6	0.58	0.58	Earthen Levee	Encroachments	LS	M	Prunings	38.974323 ° -121.481754 °	38.974323 ° -121.481754 °		15
7	0.81	0.81	Earthen Levee	Encroachments	LS	M	Debris	38.973605 ° -121.485728 °	38.973605 ° -121.485728 °		7
8	1.24	1.24	Earthen Levee	Encroachments	LS	M	Prunings	38.970720 ° -121.492475 °	38.970720 ° -121.492475 °		8
9	1.77	1.77	Earthen Levee	Encroachments	LS	CO	Landscaping	38.970353 ° -121.501935 °	38.970353 ° -121.501935 °		10
10	1.78	1.78	Earthen Levee	Encroachments	LS	CO	Buildings	38.970347 ° -121.502027 °	38.970347 ° -121.502027 °		11
11	1.79	1.81	Earthen Levee	Encroachments	LS	PO	Landscaping	38.970347 ° -121.502177 °	38.970327 ° -121.502618 °		12

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2008 Levee Inspection Results**

**Reclamation District No. 1001**

Waterway		Bank	Unit Miles
Unit No. 03 Bear River		Left	12.60

  

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	3/20/2008		9/24/2008	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By				
Unit Maintenance Rating (Fall Only)			M	

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

## Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


**X**

Signature of LMA Representative

Date



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2008**

**Reclamation District No. 1001**

Waterway						Bank	Unit Miles	Inspection Date		Inspector	
Unit No. 03 Bear River						Left	12.60	09/24/2008		Clay Thomas	
LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.65	0.65	Earthen Levee	Slope Stability	LS	M	Repair the levee slope damaged by vehicle traffic and prevent access where possible.	39.006343 ° -121.386813 °	39.006343 ° -121.386813 °		3
2	1.47	1.47	Earthen Levee	Slope Stability	CR	M	Repair slope instability.	39.002848 ° -121.400285 °	39.002848 ° -121.400285 °		4
3	3.94	3.94	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	38.991174 ° -121.441600 °	38.991174 ° -121.441600 °		28
4	4.11	4.11	Earthen Levee	Encroachments	LS	M	Prunings	38.991475 ° -121.444728 °	38.991475 ° -121.444728 °		5
5	4.51	4.54	Earthen Levee	Encroachments	LS	M	Debris	38.991918 ° -121.452003 °	38.991865 ° -121.452612 °		6
6	4.63	4.69	Earthen Levee	Vegetation	LS	M	Elderberries are blocking visibility and flood fight capability.	38.991638 ° -121.454323 °	38.991511 ° -121.455359 °		30
7	4.76	4.76	Earthen Levee	Encroachments	LS	M	Debris	38.991295 ° -121.456553 °	38.991295 ° -121.456553 °		7
8	4.99	4.99	Earthen Levee	Encroachments	LS	M	Prunings	38.989998 ° -121.460608 °	38.989998 ° -121.460608 °		32
9	5.45	5.45	Earthen Levee	Encroachments	LS	M	Firewood	38.986713 ° -121.468257 °	38.986713 ° -121.468257 °		8
10	5.68	5.68	Earthen Levee	Encroachments	LS	M	Prunings	38.986638 ° -121.472476 °	38.986638 ° -121.472476 °		33
11	6.15	6.23	Earthen Levee	Encroachments	LS	M	Firewood	38.984788 ° -121.480868 °	38.984632 ° -121.482345 °		9
12	6.38	6.38	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	38.984295 ° -121.485037 °	38.984295 ° -121.485037 °		34
13	6.62	6.62	Earthen Levee	Encroachments	LS	M	Firewood	38.983927 ° -121.489528 °	38.983927 ° -121.489528 °		11
14	6.73	6.73	Earthen Levee	Encroachments	LS	M	Prunings	38.983545 ° -121.491485 °	38.983545 ° -121.491485 °		12
15	6.88	6.96	Earthen Levee	Encroachments	LS	M	Prunings	38.983423 ° -121.494277 °	38.983277 ° -121.495640 °		13
16	7.38	7.38	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.982512 ° -121.503423 °	38.982512 ° -121.503423 °		15
17	7.54	7.54	Earthen Levee	Encroachments	LS	M	Debris	38.982095 ° -121.506367 °	38.982095 ° -121.506367 °		16
18	7.71	7.71	Earthen Levee	Encroachments	LS	M	Prunings	38.980960 ° -121.509018 °	38.980960 ° -121.509018 °		17
19	8.21	8.21	Earthen Levee	Encroachments	LS	M	Prunings	38.975700 ° -121.515462 °	38.975700 ° -121.515462 °		18

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2008**

**Reclamation District No. 1001**

Waterway						Bank	Unit Miles	Inspection Date		Inspector	
Unit No. 03 Bear River						Left	12.60	09/24/2008		Clay Thomas	
LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
20	10.01	10.01	Earthen Levee	Encroachments	CR	PO	Equipment Inspector Comments: levee blocked for new bridge construction	38.969410 ° -121.542127 °	38.969410 ° -121.542127 °		35
21	10.25	10.25	Earthen Levee	Encroachments	CR	PO	Equipment Inspector Comments: levee blocked for new bridge construction	38.966620 ° -121.543724 °	38.966620 ° -121.543724 °		36
22	10.52	10.65	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.963130 ° -121.545647 °	38.961328 ° -121.546653 °		20
23	11.29	11.32	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.953367 ° -121.551428 °	38.953025 ° -121.551808 °		22
24	12.03	12.59	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.948842 ° -121.562456 °	38.941793 ° -121.567261 °		37
25	12.15	12.15	Earthen Levee	Encroachments	LS	M	Prunings	38.947422 ° -121.563420 °	38.947422 ° -121.563420 °		26
26	12.18	12.22	Boat Survey	Boat Survey Erosion	LS	U	Inspector Comments: seepage, beaver holes, tree hazards, tension cracks, slumping	38.947043 ° -121.563686 °	38.946477 ° -121.564094 °		901
27	12.24	12.24	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.946248 ° -121.564220 °	38.946248 ° -121.564220 °		27
28	12.27	12.59	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.945849 ° -121.564456 °	38.941794 ° -121.567260 °		38

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2008 Levee Inspection Results**

**Reclamation District No. 1001**

Waterway		Bank	Unit Miles
Unit No. 04 Feather River		Left	13.30

  

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	3/27/2008		9/24/2008	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By				
Unit Maintenance Rating (Fall Only)			M	

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

## Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


X

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2008**

**Reclamation District No. 1001**

Waterway						Bank	Unit Miles	Inspection Date		Inspector	
Unit No. 04 Feather River						Left	13.30	09/24/2008		Clay Thomas	
LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.02	0.20	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.941275 ° -121.567527 °	38.938707 ° -121.567759 °		28
2	0.02	0.20	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.941276 ° -121.567527 °	38.938706 ° -121.567760 °		27
3	0.14	0.44	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.939520 ° -121.567830 °	38.935363 ° -121.567005 °		3
4	0.57	0.65	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.933415 ° -121.567152 °	38.932337 ° -121.567095 °		4
5	0.65	0.76	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.932337 ° -121.567095 °	38.930785 ° -121.567350 °		5
6	0.81	0.96	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.930202 ° -121.567765 °	38.928012 ° -121.568121 °		30
7	0.81	0.96	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.930203 ° -121.567764 °	38.928011 ° -121.568121 °		29
8	1.25	1.37	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.923933 ° -121.568608 °	38.922135 ° -121.568857 °		7
9	1.49	1.72	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.920422 ° -121.569138 °	38.917197 ° -121.569750 °		8
10	2.14	2.14	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.912007 ° -121.573242 °	38.912007 ° -121.573242 °		10
11	2.26	2.26	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.910580 ° -121.574238 °	38.910580 ° -121.574238 °		11
12	2.85	2.85	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.903948 ° -121.580242 °	38.903948 ° -121.580242 °		12
13	3.22	3.22	Earthen Levee	Encroachments	LS	PO	Landscaping	38.899732 ° -121.584110 °	38.899732 ° -121.584110 °		31
14	6.48	6.48	Earthen Levee	Encroachments	LS	PO	Landscaping	38.865653 ° -121.619742 °	38.865653 ° -121.619742 °		17
15	6.64	6.64	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.863700 ° -121.621198 °	38.863700 ° -121.621198 °		18
16	6.66	6.66	Earthen Levee	Encroachments	LS	M	Prunings	38.863385 ° -121.621342 °	38.863385 ° -121.621342 °		19
17	8.72	8.72	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.835698 ° -121.634070 °	38.835698 ° -121.634070 °		20
18	9.74	9.74	Earthen Levee	Encroachments	WS	PO	Landscaping	38.833088 ° -121.635103 °	38.833088 ° -121.635103 °		21
19	11.15	11.15	Earthen Levee	Vegetation	LS	M	Elderberries are blocking visibility and flood fight capability.	38.802508 ° -121.632862 °	38.802508 ° -121.632862 °		22

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2008**

**Reclamation District No. 1001**

Waterway							Bank	Unit Miles	Inspection Date	Inspector	
Unit No. 04 Feather River							Left	13.30	09/24/2008	Clay Thomas	
LMR Line	Levee Mile		Category	Item	* Location	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
20	11.32	11.32	Earthen Levee	Vegetation	LS	M	Elderberries are blocking visibility and flood fight capability.	38.800112 ° -121.632242 °	38.800112 ° -121.632242 °		23
21	11.81	11.84	Boat Survey	Boat Survey Erosion	LS	M	Inspector Comments: tree hazards, slumping, seepage	38.793742 ° -121.628514 °	38.793394 ° -121.628156 °		916
22	12.40	12.40	Earthen Levee	Vegetation	LS	M	Elderberries are blocking visibility and flood fight capability.	38.787355 ° -121.621165 °	38.787355 ° -121.621165 °		24
23	12.57	12.57	Earthen Levee	Encroachments	LS	CO	Buildings	38.786073 ° -121.618522 °	38.786073 ° -121.618522 °		25
24	12.74	13.22	Earthen Levee	Vegetation	LS	M	Elderberries are blocking visibility and flood fight capability.	38.784513 ° -121.616045 °	38.781862 ° -121.607855 °		26

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2008 Levee Inspection Results**

**Reclamation District No. 1001**

Waterway			Bank	Unit Miles
Unit No. 05 Natomas Cross Canal			Right	5.40
	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	4/1/2008		9/24/2008	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2008**

**Reclamation District No. 1001**

Waterway						Bank	Unit Miles	Inspection Date	Inspector
Unit No. 05 Natomas Cross Canal						Right	5.40	09/24/2008	Clay Thomas

  

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.83	0.83	Earthen Levee	Encroachments	WS CO	Buildings		38.790830 ° -121.596973 °	38.790830 ° -121.596973 °		3

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2008 Levee Inspection Results**

**Reclamation District No. 1001**

Waterway		Bank	Unit Miles
Unit No. 06 East Side Canal		Right	4.80

  

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	4/1/2008		9/24/2008	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By				
Unit Maintenance Rating (Fall Only)			M	

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


**X**

Signature of LMA Representative

Date



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2008**

**Reclamation District No. 1001**

Waterway							Bank	Unit Miles	Inspection Date	Inspector	
Unit No. 06 East Side Canal							Right	4.80	09/24/2008	Clay Thomas	
LMR Line	Levee Mile		Category	Item	* Location	* Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	1.06	1.06	Earthen Levee	Encroachments	LS	PO	Landscaping	38.845643 ° -121.524363 °	38.845643 ° -121.524363 °		5
2	1.37	1.37	Earthen Levee	Encroachments	LS	PO	Equipment	38.850042 ° -121.524359 °	38.850042 ° -121.524359 °		6
3	1.45	1.45	Earthen Levee	Encroachments	LS	PO	Equipment	38.851272 ° -121.524357 °	38.851272 ° -121.524357 °		3
4	3.29	3.29	Interior Drainage & Piping Systems	Sluice / Slide Gates	WS	M	Inspector Comments: Gate appears to be closed, gate stem is damaged	38.877680 ° -121.524760 °	38.877680 ° -121.524760 °		4
5	4.41	4.74	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.893872 ° -121.524708 °	38.896340 ° -121.520492 °		8
6	4.41	4.74	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.893873 ° -121.524707 °	38.896340 ° -121.520492 °		7

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected